


# Cavity Types GB



## 1 Machining notes



### ATTENTION!

You must maintain the specified positional and diametral tolerances. To ensure trouble-free operation of the screw-in cartridges, we strongly recommend that pilot drilling, boring, reaming and cavity thread-cutting are always performed in one setup.



### IMPORTANT!

We offer form tool sets for sale or hire. For further information, see data sheet 400-P-040011-EN.



### ATTENTION! 1)

It is essential that the G1/4" thread be cut with a tap. Thread milling is not permitted, because the circular interpolation can produce unacceptable roundness errors.

info.ch@bucherhydraulics.com

www.bucherhydraulics.com

© 2015 by Bucher Hydraulics AG Frutigen, CH-3714 Frutigen

All rights reserved.

Data is provided for the purpose of product description only, and must not be construed as warranted characteristics in the legal sense. The information does not relieve users from the duty of conducting their own evaluations and tests. Because the products are subject to continual improvement, we reserve the right to amend the product specifications contained in this catalogue.

Classification: 430.Info. ...

Reference: 400-P-040311-EN-00